

Chichester District Council

Heritage At Risk Register

Bedham Mission Church & School **BEDHAM**

Asset Type:	Unlisted Building
Grid Reference:	501604, 121988
Parish:	Bedham
Conservation Area:	No
SDNP:	Yes
Description:	1880 single-cell nonconformist chapel/school built by William Townley Mitford MP of Pitshill.
Priority:	C
Reason for Risk:	General deterioration.
Registered:	
Last Assessed:	19 April 2012
Ownership:	
Current Status:	Derelict building without roof. Internal floor missing. 1 window remains (without glass). External stone and brick skin in reasonable condition, though requires repointing, particularly along the south-west elevation. Internal brick spalling on upper part of walls in places. Excessive loss of lime mortar within. Walls are capped. Metal shoring to north west wall.

Photograph 2012



Priority

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user. (Applicable only to buildings capable of beneficial use.)
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.