

Chichester District Council

Heritage At Risk Register

Carmelite Convent HUNSTON

Asset Type:	Unlisted Building
Grid Reference:	486787 103327
Parish:	Hunston
Conservation Area:	No
SDNP:	No
Description:	19C Convent for nuns of a silent order. Quadrangle building with chapel to east. Walled garden to south.
Priority:	C
Reason for Risk:	General deterioration. Structural movement. Vulnerable.
Registered:	August 2002
Last Assessed:	7 August 2012
Ownership:	Private
Current Status:	Building secure. Exterior in generally good condition, some cracking to north and east elevations due to structural movement. Failure of water goods causing damp to elevation. Extensive fire damage to chapel. Internally, water ingress and damp throughout.

Photograph 2012



Priority

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user. (Applicable only to buildings capable of beneficial use.)
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.